L1	FILE	CAPLUS' ENTERED AT 10:28:15 ON 22 MAY 2010 231 SEA SPE=ON ABB=ON PLU=ON (PRESSFELT OF	R PRESS-FELT OR (PRESS
L2		FELT))  0 SEA SPE=ON ABB=ON PLU=ON L1 AND ((PAR'	
L3		OR POWDER) (5A) (SOFTEN? OR FLOW? OR FUSION SEA SPE=ON ABB=ON PLU=ON L1 AND ((PAR'OR POWDER) (10A) (SOFTEN? OR FLOW? OR FUSION.)	TICLE OR PARTICULATE
L4		0 SEA SPE=ON ABB=ON PLU=ON L1 AND ((PAR' OR POWDER) AND (SOFTEN? OR FLOW? OR FUSE	TICLE OR PARTICULATE
L5	FILE	WPIX' ENTERED AT 10:30:35 ON 22 MAY 2010 495 SEA SPE=ON ABB=ON PLU=ON (PRESSFELT OF	R PRESS-FELT OR (PRESS
L6		3 SEA SPE=ON ABB=ON PLU=ON L5 AND ((PAR' OR POWDER) (10A) (SOFTEN? OR FLOW? OR FU: D 1-3 FULL	
	FILE	JAPIO' ENTERED AT 10:33:40 ON 22 MAY 2010	
L7		71 SEA SPE=ON ABB=ON PLU=ON (PRESSFELT OF FELT))	R PRESS-FELT OR (PRESS
L8		0 SEA SPE=ON ABB=ON PLU=ON L7 AND ((PAR' OR POWDER) (10A) (SOFTEN? OR FLOW? OR FU	
L9		O SEA SPE=ON ABB=ON PLU=ON L7 AND ((PAR OR POWDER) AND (SOFTEN? OR FLOW? OR FUSE	TICLE OR PARTICULATE
	FILE	TEXTILETECH, WTEXTILES' ENTERED AT 10:34:33 O	N 22 MAY 2010
L10		29 SEA SPE=ON ABB=ON PLU=ON (PRESSFELT OF FELT))	
L11			R PRESS-FELT OR (PRESS
	TOTAL	FOR ALL FILES	
L12		FELT))	R PRESS-FELT OR (PRESS
L13		O SEA SPE=ON ABB=ON PLU=ON L10 AND ((PA	
L14		OR POWDER) (10A) (SOFTEN? OR FLOW? OR FU:  1 SEA SPE=ON ABB=ON PLU=ON L11 AND ((PAI OR POWDER) (10A) (SOFTEN? OR FLOW? OR FU:	RTICLE OR PARTICULATE
	TOTAL	FOR ALL FILES	
L15		1 SEA SPE=ON ABB=ON PLU=ON L12 AND ((PA) OR POWDER) (10A) (SOFTEN? OR FLOW? OR FU: D ALL	
	FILE	CAPLUS, WPIX' ENTERED AT 10:37:24 ON 22 MAY 2	010
L16		O SEA SPE=ON ABB=ON PLU=ON EO342171/PN	
L17	TOTAL	0 SEA SPE=ON ABB=ON PLU=ON EO342171/PN FOR ALL FILES	
L18		0 SEA SPE=ON ABB=ON PLU=ON EO342171/PN	
L19		O SEA SPE=ON ABB=ON PLU=ON EP342171/PN	
L20	т∩тът	1 SEA SPE=ON ABB=ON PLU=ON EP342171/PN FOR ALL FILES	
L21	TOTAL	1 SEA SPE=ON ABB=ON PLU=ON EP342171/PN D FULL	